FIG. 1A



FIG. 1B




FIG. 1C





FIG. 1D






FIG. 1F

14a

14

13f

13e

13d

13c


13b

13a

12

11

15a




APPROVED O.G. FIG.

BY CLASS SUBCLASS


DRAFTS: AN

FIG. 1H




DPAFTSMAN

O.G. FIG.



COCHET BESEVACO

FIG. 3



CACATA BECKAPO

FIG. 4A




FIG. 4B





FIG. 5



NUMBER OF BUBBLE DEFECTS(RATIO)

SIH OF HSQ FILM(%)


APPROVED	Q.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

=1G. 6

O.G. FIG.

DRAFTSMAN


SUBCLASS



O:G. FIG.

APPROVED

DRAFTSMAN



NUMBER OF BUBBLE DEFECTS (RATIO)

WET ETCHING AMOUNT(Å)

ru Tu

ū

ō

FIG. 8A




FIG. 8B




FIG. 8C

